












Date: Thursday, 18/09/2008 8:53:39 AM
 User: Julie Lecocq

Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: HEAD REST ASSEMBLY LH
Job Number	: 42086		
Estimate Number	: 10859		
P.O. Number	:	Part Number	: D412724043
This Issue	: 18/09/2008	S.O. No.	:
Prsht Rev.	: NC	Drawing Number	: N/A
First Issue	: / /	Project Number	: N/A
Previous Run	: 40818	Drawing Revision	: N/A
	Type : SMALL /MED FAB	Material	:
Written By	:	Due Date	: 30/09/2008
Checked & Approved By	: <u>JUL 08.9.18</u>	Qty:	1 Um: Each
Comment	: Est Rev:A 04.09.08 New Issue KJ/JLM		
Additional Product			
Job Number: 			
Seq. #:	Machine Or Operation:	Description :	
1.0	DC	DOCUMENT CONTROL	
			
Comment: DOCUMENT CONTROL If D412-724-043 is a W/O on it's own, Photocopy bluefile and create labels per PPP D412-724-043 CHG001 <i>NA KJ</i>			
2.0	PACKAGING 1	PACKAGING RESOURCE #1	
			
Comment: PACKAGING RESOURCE #1 Pick Packing Kit			
3.0	D3303041	Head Rest	
			
Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch <u>41188 40859</u> <i>SS 08/10/21 (X)</i>			
4.0	D3304043	Tube Assembly	
			
Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch <u>40864 40861</u> <i>SS 08/10/21 (X)</i>			
5.0	AN52510R6	Screw	
			
Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch <u>M10/203</u> <i>SS 08/10/21 (X)</i>			

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 18/09/2008 8:53:39 AM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: HEAD REST ASSEMBLY LH

Job Number: 42086

Part Number: D412724043

Job Number:



Seq. #:

Machine Or Operation:

Description :

4 AN525-10R6 Screw

6.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT 100% KITS FOR COMPLETENESS

08/10/22

7.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D412-724-043

Location:

PPP Rev:

PPP 40885

SS 08/10/22

8.0

QC21

FINAL INSPECTION/W/O RELEASE



08/10/22

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



MF 08-10-22

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries